

COURSE : PHYSICAL METALLURGY 2


Prepared by Pr. Zakaria Boumerzoug

Lecture 1: Introduction to Phase Diagram Fe-C.


Iron :

- Iron is a metal
- It has an atomic weight of 56
- It is the most-used and cheapest metal.


The structure : Three **allotropic** forms of iron exist, depending on temperature: **alpha** iron (α -Fe), **gamma** iron (γ -Fe), and **delta** iron (δ -Fe).




Phase Diagram



Austenite



Ferrite



Pearlite = Ferrite + Cementite

Definitions of phases :

Definition 1 : α -ferrite -solid solution of C in Fe (BCC)

Definition 2 : γ -austenite -solid solution of C in FCC Fe


Definition 3 : δ -ferrite solid solution of C in BCC Fe

Definition 4 : Fe_3C (iron carbide or cementite)

Definition 5 : Maximum solubility in BCC α -ferrite is limited (max. 0.022 wt% at 727 °C)

Definition 6 : Maximum solubility in FCC austenite is 2.14 wt% at 1147 °C-FCC has larger interstitial positions.


Phase transformation at solid state :



During a low cooling rate :

We have a transformation from Austenite to Pearlite

Austenite \rightarrow Pearlite



Pearlite = Ferrite + Cementite

Lecture 2: Some phase transformations in Fe-Fe₃C

(Reference : <https://mech.poriyaan.in/topic/iron-iron-carbide-equilibrium-diagram-30655>)






Fig. 1.25. The iron-iron carbide phase diagram

1- Pearlitic transformation





2- Slow cooling of Hypoeutectoid Steel



Ferrite


Pearlite

3- Slow cooling of an Hypereutectoid steel





Lecture 3 Martensitic transformation

During rapid cooling (quenching) of austenite, a martensitic transformation begins at the martensite start temperature (M_s).




Lecture 4 : Diagram TTT

(Reference : <https://www.metallurgyfordummies.com/time-temperature-transformation-ttt-diagram.html>)



Austenite



Pearlite






Martensite



Bainite


Lecture 5 Cast Iron







Graphite

pearlite




Cementite:
white phase


Graphite




Lecture 6 TTT Diagram

<https://www.metallurgyfordummies.com/fe-fe3c-t-t-t-diagram.html>








Construction of Isothermal Transformation Diagram



Cooling curves superimposed on a hypothetical I-T diagram




Microstructures in a eutectoid steel. (a) Pearlite formed at 720 °C, (b) bainite formed at 290 °C, (c) bainite formed at 180 °C, and (d) martensite



Lecture 07: TTT and CCT Diagrams

- I- TTT diagram Eutectoid, Hypoeutectoid and Hypereutectoid steel

1- TTT Diagram for Eutectoid Steel :








Fig 2.3: TTT diagram of eutectoid steel







Azom.com™

The TTT diagram for AISI 1080 steel (0.79%C, 0.76%Mn) austenitised at 900°C.

Ref: <https://www.azom.com/article.aspx?ArticleID=313>

2-TTT diagram of Hypoeutectoid steel





3-TTT diagram of Hypereutectoid steel





FIGURE 10.15 TTT diagram for a hypereutectoid composition (1.13 wt % C) compared with the Fe-Fe₃C phase diagram. Microstructural development for the slow cooling of this alloy was shown in Figure 9.39. (TTT diagram after Atlas of Isothermal Transformation and Cooling Transformation Diagrams, American Society for Metals, Metals Park, OH, 1977.)

II- Continuous cooling transformation (CCT) diagram

Continuous cooling transformation (CCT) diagrams


Measure the extent of transformation as a function of time for a continuously decreasing temperature. In other words a sample is austenitised and then cooled at a predetermined rate and the degree of transformation is measured, for example by dilatometry. Obviously a large number of experiments is required to build up a complete CCT diagram.



<https://steelselector.sij.si/help/testing/ttt.html>

Lecture 8 Tempering of steel

Tempering is usually performed after quenching. After quenching the steel is hard, brittle and internally stressed. It is applied to improve its mechanical characteristics, as well as to reduce the internal stresses. Tempering is accomplished by controlled heating of the quenched workpiece to a temperature below its "lower critical temperature".



The main types of tempering

Low-temperature tempering

, Low-temperature tempering is used to form tempered martensite at 150-200°C

When tempering is performed, the internal strain in the steel is relieved or eliminated, and the precipitation effect of carbides is promoted, resulting in improved quality.

High-temperature tempering

High temperature tempering is when we use temperatures higher than 500 °C.

- There is also **tempering at medium temperatures**. (Between the **Low-temperature tempering** and **High-temperature tempering**)

Effect of temperature of tempering in mechanical properties of steel :

Tempering curves, which are plots of hardness against tempering temperature. exist for all commercial steels and are used to select the correct tempering temperature.

As the tempering temperature increases, the hardness decreases





Figure 11 – Effect of time at tempering temperature on the hardness of 0.8% carbon steel [1, 2].

The other mechanical properties are also affected :



Ref : <https://www.tec-science.com/material-science/heat-treatment-steel/quenching-and-tempering/>

The hardness variation during tempering treatment , the percentage of carbon can also affect the hardness variation :




Figure 10 – Effect of tempering temperature on the hardness of carbon steels of different carbon content. Specimens were tempered for 1 hour [1, 2]

Ref : <https://www.chengxinspringsteel.co.za/steel-heat-treatment.html>

This course is prepared from different sources